



Introducing...
Visibowl™

High quality, low cost air filter Pre-Cleaners!



Visibowl™ offers:

- Ease of installation
- Rubber reducers combined with pre-cleaner units to cover most air intake sizes
- Manufactured with UV stabilized polymer to prevent discoloration and cracking
- Replacement bowls interchangeable with Donaldson® full view pre-cleaners
- Four common sizes enable lower inventory stock levels to cover Customer needs



Visibowl™ Pre-Cleaners

Visibowl™ P/N	Description	Air Flow (CFM)	Inlet Size (inches)	Donaldson® P/N
AP0200/3920138S	Pre-cleaner assembly	30-60	1.38"	H002041
AP0200/3920175S	Pre-cleaner assembly	30-80	1.75"	H002042
AP0200	Pre-cleaner assembly	30-90	2.0"	H002040
AP0300/3930200S	Pre-cleaner assembly	80-110	2.0" HF	H001823
AP0300/3930225S	Pre-cleaner assembly	80-130	2.25"	H001250
AP0300/3930250S	Pre-cleaner assembly	80-150	2.5"	H001251
AP0300	Pre-cleaner assembly	80-170	3.0"	H001249
AP0450/3945300S	Pre-cleaner assembly	150-320	3.0" HF	H000820
AP0450/3945375S	Pre-cleaner assembly	150-330	3.75"	H000821
AP0450/3945400S	Pre-cleaner assembly	150-340	4.0"	H000858
AP0450	Pre-cleaner assembly	150-340	4.5"	H000823
AP0500/3950400S	Pre-cleaner assembly	330-660	4.0" HF	H002045
AP0500/3950450S	Pre-cleaner assembly	330-700	4.5" HF	H002044
AP0500	Pre-cleaner assembly	330-740	5.0"	H002043
3910200S	Replacement bowl for AP0200			P02-0115
3910300S	Replacement bowl for AP0300			P02-0227
3910450S	Replacement bowl for AP0450			P01-6330
3910500S	Replacement bowl for AP0500			P02-0344

Replacement Parts

3910200S	Replacement bowl for AP0200
3910300S	Replacement bowl for AP0300
3910450S	Replacement bowl for AP0450
3910500S	Replacement bowl for AP0500
3950600S	Expansion adapter for AP0500 – 5.0" to 6.0"
3920175S	Reducing sleeve for AP0200 – 2.0" to 1.75"
3920138S	Reducing sleeve for AP0200 – 2.0" to 1.38"
3930250S	Reducing sleeve for AP0300 – 3.0" to 2.5"
3930225S	Reducing sleeve for AP0300 – 3.0" to 2.25"
3930200S	Reducing sleeve for AP0300 – 3.0" to 2.0"
3945400S	Reducing sleeve for AP0450 – 4.5" to 4.0"
3945375S	Reducing sleeve for AP0450 – 4.5" to 3.75"
3945300S	Reducing sleeve for AP0450 – 4.5" to 3.0"
3950450S	Reducing sleeve for AP0500 – 5.0" to 4.5"
3950400S	Reducing sleeve for AP0500 – 5.0" to 4.0"

To order, call your Customer Assistance Representative at **1-800-22FILTER**
(1-800-223-4583), fax 1-800-999-8664, or visit us at www.fleetguard.com

